

*Returned to Sanitary
Services
File*

March 10, 1975

Mr. Walter Paul Rosseau
1931 S. Robberson
Springfield, Missouri 65802

Dear Mr. Rosseau:

On a recent occasion, surveillance and enforcement personnel from this office investigated a complaint and found that a substance resembling crank case oil had apparently been drained into the storm sewer in front of your residence. This office has no way of knowing who might be responsible.

Let me advise you that if this spillage is due to any activities on your part, this constitutes violations of City, State and Federal Laws. These laws contain severe penalties for the discharge of oil or petroleum products. This office maintains periodic surveillance throughout the corporate limits of the City and will watch this area closely. If the discharge described is not due to any activity on your part, you can help significantly by reporting any such activities immediately to this office.

If we may be of any assistance or can answer any questions, please do not hesitate to call.

Yours truly,

J. Randall Lyman

J. Randall Lyman
Water Pollution Control Inspector
Surveillance & Enforcement

JRL:sw

cc: Mr. Jim Burris, Regional Engineer, Dept. of Natural Resources
Public Works File

1931 S. Robberson